

Imray Correction Notice

12 August 2011

Chart 2000+9 WGS 84

Edition Jul 2004

Date of printing Jul 2004

The following corrections should be noted:

1 Rivers Crouch (*reinstated - see ILNW 110/05*)

Delete power cable and 4 spher Y buoys centred on 51°37'·25N 0°50'·13E (ILNW 323/04)

2 River Roach, Havengore Bridge

Starting 21.3.05 for a period of approximately seven weeks, Havengore Bridge will be closed for maintenance work. Access to Rivers Crouch and Roach must be made via Whitaker Channel. (ILNW 98/05)

3 River Roach (as at 31.3.05)

Re-instate power cable and 4 spher Y buoys centred on 51°37'·25N 0°50'·13E (ILNW 110/05)

4 Havengore Creek (w.e.f 21.3.06)

Havengore bridge will be closed for approx 7 weeks. Access to Crouch Hbr will be via the Whitaker Channel during this time. (ILNW 79/06)

5 River Roach at Paglesham

Mariners are warned that the five Fairway buoys at Paglesham are to be removed for maintenance between 16 October and 31 October 2006 (subject to weather conditions). (ILNW 402/06)

6 River Crouch, Ness Hole

Insert dangerous wk sym in 51°37'·07N 0°52'·61E, plus isolated danger pillar Lt buoy FI(2)5s close N. (ILNW 14/10)

7 River Crouch – Revisions to Buoyage

Mariners are advised that, as of 15th July 2011, the re-buoysing of the River Crouch and approaches has been completed.

Full details will be included on a forthcoming edition of this chart. In the meantime, the chartlet on the Crouch Harbour Authority website (www.crouchharbour.org.uk) should be consulted for new buoy positions. (ILNW 265/11)

8 Notification of New Edition

A new August 2011 edition of this sheet will shortly be published. In addition to the listed corrections, this edition shows the revised buoyage into the River Crouch, plus uses the latest available survey data throughout. (ILNW 278/11)